

Ajustes

①

②

③

④

ICIC Ø3.5

MAX 1

CH4

+2.5 ↑ Z

-2.5 ↓ Z

+3 ↑ X

-1.5 ↓ X

①

②

③

MAX 1

CH4

+1 ↑ Y

-1 ↓ Y

Abertura 0°

24^{+0.5}₀

*D

*D

24^{+0.5}₀

Sp. min. 32

5⁰_{-0.5}

7⁰_{-0.5}

21⁺¹₀

27⁺¹₀

3⁺³_{-1.5}

Sp. min.	*D
32	4
35	5

Abertura 90°

2.2

90°

Abertura 180°

3.4⁺¹

11